autologic

Data Update 1.0 - Mar 2016

Type	Change	Vehicle / Model
BMW		**Download Ref : BMW148**
Enhancement	BDC replacement function added (to allow replacement of BDC/lockset without a Vehicle Order import patch from the support team)	X5 F15
Enhancement	Learning zero-gear sensor function added to DME MV1722 (required after ECU replacement)	Mini R57
Enhancement	New variant of NBT for F-Series	F - series
Improvement	Set automatic driving lights control conversion for R56	Mini R56
Enhancement	Teaching in Telestart function added to IHKA25_2 variant for F series (required for ECU replacement)	X3 F25
Enhancement	Airmass system test added for DDE7.3 N57a	F - series
Improvement	Added Auxiliary heating retrofit on F15	X5 F15
Improvement	Update for Exhaust VANOS test on DME MSV80	3 - series E90
Improvement	Update for SCR reset function on DDE7.3 N57c	3 -series E90
Improvement	Update for Secondard Air pump relay activation on DME MS43.0	3 - seriesE46
Improvement	Update for Snapshot data on Mini DME MVD1722	Mini R56
Enhancement	Bypass flap, EGR cooler activation added to DDE7.3 N57c	3 - series E90
Enhancement	Variant added to DDE7.1 N47a air mass test	Mini R56
Improvement	Diagnostics updated for convertible module CVM59	Mini R56
Improvement	Fault code descriptions updated for 171 F-Series control unit variants	F - series
Improvement	F-Series energy diagnosis logging improved	F - series
Enhancement	Guidance notes added to Oxygen sensor test on MSS60	3 -series E90
Improvement	Headlight initialisation function updated for all F series models	F - series
Improvement	Idle speed adjustment updated for DME MS45.0	3- series E46
Improvement	Improvements made to the Autologic's automatic vehicle determination feature	X5 F15
Improvement	Minimum valve lift function updated for DME ME9 N62 engine	7-series E65
Improvement	SCR adjustment function updated for SCR	X5 F15
VAG		**Download Ref : VAG89**
Improvement	Improved ECU replacement function for all vehicles.	All models
Improvement	Improved messaging following successful ABS basic settings for VW Golf 7	VW Golf 2013+
Improvement	Improved service function reset for all variants of VW Jetta 2014	VW Jetta
Improvement	Added DPF function for VW Transporter 2012	VW Transporter
Improvement	Improved functionality for all engine replacements on Assist+ units	All models
Improvement	Improved fault code reports	Audi A6's (4G), Audi A7's, Audi A8's and VW Touaregs
Enhancement	Enhanced engine electronics function list to include Ash Mass Quantity Calibration	Audi A6
Enhancement	Enhanced instructions for Secondary Air System Test	Audi Q5

Jaguar		Download Ref : JAG45
Improvement	X250_08 XF 2008 - Modification to SODR configuration.	XF X250 2008
Enhancement	X100 XK - Updated fault descriptions for adaptive speed control module BCM.	XK X100
Improvement	X250_08 XF 2008 - Changed the SBL used for diesel PCM CCF write	XF X250 2008
Land Rover		**Download Ref : LR63**
Enhancement	L322_10 Range Rover 2010 - Added power steering curves.	Range Rover 2010 L322
Enhancement	L538_12 Range Rover Evoque 2012 - Added CCF options for tyre size.	Range Rover Evoque 2012 L538
Improvement	L316_12 Defender 2013 - Corrected Fuel rail pressure dynamic.	Defender 2013 L316
Improvement	L494 Range Rover Sport 2014 - TDV6 Corrected DPF regen function.	Range Rover Sport 2014 L494
Mercedes		**Download Ref : MERC154**
Enhancement	Added new guided test for CDR3: Boost pressure positioner	CLA(117), A(176), B(246), C(204), CLS(218), E(212), GLA(156), ML(166), S(221), SLK(172)
Enhancement	Added new guided test for ME-SFI on A(169): guided test for Y101	B(245)
Improvement	Updated Actual values for HVAC_246	A(176), B(246), CLA(117), GLA(156)
Improvement	Updated Actual values for SDAR221	B(246), C(204), CL(216), CLA(117), E(212), G(463), ML(166), S(221), SL(231), SLK(172), SLS(197)
Enhancement	Added new adaptation for SCR: teach in process	S(221)
Improvement	Updated Fuel tank sender coding for ICM on A(168)	Vaneo 414
Improvement	Updated Actuation for MED40AMG: M4/7 (COMBUSTION ENGINE AND AIR CONDITIONING WITH INTEGRATED CONTROL FAN MOTOR)	CLA(117), A(176), GLA(156)
Improvement	Updated Adaptation for CR60LS: Teach in for RESET LEARNED VALUES FOR ADBLUEÂ® METERING	ML(166)
Improvement	Updated Adaptation for CRR1: RESETTIN OF LEARNED VALUES 'FULE INJECTORS'	CLA(117), A(176), B(246), GLA(156)
Improvement	Updated Adaptation for CGW on C(204): Variant coding	E(212)
Improvement	Updated actual values for SAMR on E(212)	C(204)
Improvement	Updated Adaptation for CRD3	B(246)
Improvement	Updated Fault list for CR60LS	ML(166)
Improvement	Updated Adaptation for FSAM on M(164): Variant coding	ML(164)
Improvement	Updated Adaptation for ME28: Variant coding	E(211)
PSA		**Download Ref : PSA51**
Improvement	Improve configuration menu for POMPE MUX MGI	207, 307 (2005-2008), C4 Picasso, Berlingo 3
Improvement	Improve configuration menu for POMPE MUX TI	308, 3008, 5008, Partner 3, RCZ, C4 Picasso, Berlingo 3
Volvo		**Download Ref : VOLVO14**
Improvement	Moved 'Vehicle Scan' button to 'Communication Tools' menu	All Volvo models
Renault		**Download Ref : RENAULT50**
Improvement	Improve the aerials actuation functions on Scenic 2	Scenic 2